GasAlert MaxXT

The durable GasAlertMax XT, with built in motorized sampling pump, reliably monitors up to four gas hazards (H_2S, CO, O_2 and combustible gases).

Customize your detector to suit specific applications and maximize performance with a wide variety of accessories.

Carrying Accessories

XT-CK / XT-CK-DL

Confined Space Kit Carrying Case / Deluxe Confined Space Kit
The durable, compact Carrying Case (XT-CK) conveniently holds your gas detector kit and everything you need for safe sampling in confined space entry work. The Deluxe Confined Space Kit (XT-CK-DL) comes equipped with: Concussion-Proof Boot; Carrying Holster; IR Connectivity Kit; 1 ft. / 0.3 m Sample Probe; 10 ft. / 3.3 m sampling hose and 3 ft. / 1 m calibration hose, both with quick-connector fitting; 0.5 LPM regulator; and space to hold your detector kit and one 34 L calibration gas cylinder.

GA-BXT

Concussion-Proof Boot
The external rubber boot keeps detectors cleaner and provides an additional level of protection in extreme conditions. The boot fits securely onto the detector and is equipped with a rugged stainless steel, alligator-style clip.

GA-HXT

Carrying Holster
Securely attach the GasAlertMax XT and tubing to your belt with the durable Carrying Holster.

GA-NS-1

Neckstrap with Safety Release
Wear the detector close to the breathing zone without hampering mobility. In the event the strap becomes caught, the safety release will break away from the Neck Strap.

GA-LY-1

Short Strap
The Short Strap (6 in. / 15.2 cm) facilitates the attachment of your gas detector to your clothing or personal protective equipment (PPE). The smaller loop attaches to buttons or other fasteners.

GA-ES-1

Extension Strap
The 4 ft. / 1.2 m extension strap attaches easily to the detector.

GASALERTMAX XT ACCESSORIES

BW Technologies
by Honeywell

Wear yellow. Work safe.

Carrying Accessories (Continued)

GA-CH-2

Chest Harness

Keep the detector secure to your chest and close to the breathing zone.
Mobility is not hampered with the Chest Harness. The harness is secured around
the user's shoulders and torso.

GA-ARM-1

Arm Band

Comfortably secure the detector to your arm with the Arm Band accessory to
ensure it is worn close to the breathing zone without hampering mobility.
The alligator clip on the detector attaches easily to the Arm Band.

Power Accessories

XT-C01-MC5-(XX)
Note: Specify plug/region version (XX): North America (NA), United Kingdom (UK), Europe (EU), China/Australia (CN)

Multi-Unit Cradle Charger

Simultaneously charge 5 detectors with the Multi-Unit Cradle Charger. Simply slip
detectors into the charger and wait for the battery icon on the LCD to indicate the
battery is fully charged.

GA-PA-1-MC5 (-XX)
Note: Specify plug/region version (-XX): North America (None), United Kingdom (-UK), Europe (-EU), China/Australia (-CN)

Multi-Unit Power Adaptor

Simultaneously charge 5 detectors with the Multi-Unit Power Adaptor. Simply connect
each adaptor to a detector's charging/IR interface and wait for the
battery icon on the LCD to indicate the battery is fully charged.

GA-VPA-1

Vehicle Power Adaptor

Charge your detector easily anywhere you go with the Vehicle Power Adaptor.
Suitable for 12V applications. Simply connect the adaptor to the detector's
charging/IR interface and charging port and wait for the battery icon on the LCD to
indicate the battery is fully charged.

GA-PA-3

12-24 V_{DC} Direct-Wire Power Adaptor

Connect directly to a 12V or 24V power system with the 12-24 V_{DC} Direct-Wire
Power Adaptor. Simply connect the adaptor to the detector's charging/IR interface.

GA-PA-1 (-XX)
Note: Specify plug/region version (-XX): North America (None), United Kingdom (-UK), Europe (-EU), China/Australia (-CN)

Replacement Power Adaptor

Ensure your detector is charged and ready for use with the IR power adaptor. Simply con-
nect the adaptor to the detector's charging/IR interface and wait for the battery icon on
the LCD to indicate the battery is fully charged. Included with detector.

Miscellaneous Accessories

GA-USB1-IR

IR Connectivity Kit
The IR Connectivity Kit easily connects to the IR communications and charging port, linking your detector to your computer for data downloads and access to instrument set-up options.

Fleet Manager II

Fleet Manager II enables users to download information directly from the GasAlertMax XT detector or the MicroDock II system. Data storage and analysis is made easy. Fleet Manager II also enables users to customize user-definable detector options. Included with IR Connectivity Kit.

Sampling/Testing Accessories

MicroDock II

The MicroDock II is the cost-effective way to manage the GasAlertMax XT. Calibration, bump testing, charging and record keeping are simplified. Fully portable, the MicroDock II requires no computer and can manage up to 6 GasAlertMax docking modules.

GA-PROB1-1

Sample Probe
The Sample Probe (1 ft. / 0.3 m) is ideal for pick hole sampling or sampling hard to reach places. The particulate filters and hydrophobic barrier prevents moisture and debris from entering the detector.

GA-PROB-FIL-K1

Filter and Gaskets Replacements for GA-PROB1-1
Replacement Hydrophobic Filters (1.0 µm), Particulate Filters and Gaskets for use with the Sample Probe to prevent moisture and particulates from entering the detector.

M0931K

Quick-Connect Fitting Spares for Sampling Hose
Attaching the tubing to the pump inlet is easy with Quick-Connect fitting. The Quick-Connect fitting spares come in a kit of 2.

GA-CPROB1 / GA-CPROB2

Collapsible Sample Probe with Handle
The Collapsible Sample Probe with Handle is ideal for pick hole sampling and sampling hard to reach places. Comes in 3.3 ft. / 1 m or 6 ft. / 1.8 m lengths.

D4-PROB1 / D4-PROB3 / D4-PROB6

Search Probe with Handle and Quick Connect
Sample remote locations with the Search Probe with Handle and Quick Connect. Attaching the tubing to the pump inlet is easy with Quick Connect fitting. Comes in 1 ft. / 0.3 m, 3 ft. / 0.9 m, or 6 ft. / 1.8 m lengths.

GASALERTMAX XT ACCESSORIES

Technologies by Honeywell

Wear yellow. Work safe.

Sampling/Testing Accessories (Continued)

GA-TPROB7

Telescopic Sample Probe
The extendable Telescopic Sample Probe (7.9 ft. / 2.4 m) can be used for remote sampling in difficult to reach areas.

GA-FLOAT

Sampling Float
For obtaining samples directly above liquids, the Sampling Float is the easy solution. The hose connects to an axel between two buoys. The inlet is elevated above the liquid surface.

GA-MFILTER

Metallic Sintered Particulate Filter
The Metallic Sintered Particulate Filter prevents dirt and debris from entering and clogging the pump.

M5-AF-K2 / M5-AF-K2-100

Auxiliary Filter for GasAlertMax XT Pump
For extremely high dust environments. The Auxiliary Filter provides extra protection for the pump. Available in a kit of 5 or 100.

XT-RF-H5 / XT-RF-H50 / XT-RF-H100

Hydrophobic Filter Replacement for GasAlertMax XT Pump
The Hydrophobic Filter Replacement can be easily inserted into the GasAlertMax XT to prevent moisture from entering the detector. Comes in kits of 5, 50 or 100.

GA-PFMAX / GA-PFMAX-50 / GA-PFMAX-100

Particulate Filter Replacement for GasAlertMax XT Pump
The Pump Particulate Filter, available in kits of 5, 50 and 100, can be easily replaced when filters in use become dirty or clogged.

Calibration/Test Equipment
A range of 7L, 34L, 58L, 103L and 900L test gas cylinders and kits are available. Calibration is only as accurate as the test gas used, therefore BW Technologies by Honeywell test gases are made to N.I.S.T. (National Institute of Standards and Technology) standards.

Contact BW Technologies by Honeywell for a full list of test gas and calibration equipment.

GASALERTMAX XT ACCESSORIES

BW Technologies by Honeywell